




# OPEN Frente ducha 1 puerta
















①		AL052	X 2	⑱		PL041	X 7
②		AL061	X 1				
③		HD030	X 1				
④		JT015	X 2				
⑤		PL075L/R	X 2				
⑥		AL016	X 1				
⑦		JT036-01	X 1				
⑧		AL054	X 1				
⑨		HD015	X 1				
⑩		A	X 1				
⑪		PL065	X 1				
⑫		PL066	X 2				
⑬		PL062	X 1				
⑭		HD031	X 1				
⑮		ST4X30	X 9				
⑯		PL063	X 4				
⑰		ST4X8	X 4				


1









2







X1









X2








3






-   X1
-  X1
-  X1



4








5











6



7

- 12 X2
- 11 X1
- 5 X2



8

